



PO Box 1150
Issaquah, WA 98027
(206) 965-5797

J. Jeffrey Huber Daily Report

10-27-2020

River Activities – Electron crew working on the fish ladder.

Construction Activities – Electron crew working in the old spillway.

JH – 0700 Electron crew on deck.

JH – 0700 Corey K. Conducts the water quality monitoring.

JH – Electron fish biologist onsite and assisting with clean up at the old spill way.

JH – 0700 Electron crew member 300' downstream to monitor for turbidity.

JH – 0930 Dept of Ecology is onsite. Carol & Jess from the Dept of Ecology are present.

JH – 1000 electron crew is continuing with the ongoing clean up of the old spillway. All turf and plastic have been hauled out at this time.

JH – 1030 Electron is excavating 300 yards of material throughout the old spillway to make sure that there is no contaminants or rubber remaining.

JH – 1300 Clean up is ongoing. Electron crew under the supervision of Corey A. starts to clean up the fish ladder. Astro – turf and plastic is removed from the outfall side. Electron crew is also digging out the conex boxes that had been filled with earth and used as coffer dams. The backfill from the dug out conex's is being used for backfill.

JH – All plastic and astro – turf is being hauled to the speeder barn area and stockpiled.

JH – 1330 Electron crew is cleaning up the upper yard at the intake. This is ongoing.

JH – 1400 Clean up of the fish ladder is ongoing.

JH – 1500 clean up of old spillway is ongoing.

JH – 1800 Electron crew continues working on the clean up with limited crew. Will push into the night to ensure clean up.



PO Box 1150
Issaquah, WA 98027
(206) 965-5797

Sincerely,

J. Jeffrey Huber
Encore Environmental
Independent Compliance Monitor on Behalf of Pierce County
Electron Hydro